



Kategorija: Veliki Servis

Remenica, radilica BTA E6I0001BTA

Šifra proizvoda: IC-F86835

Cena: 15541.3 RSD

*u cenu je uračunat PDV

Crankshaft pulley fits: LAND ROVER FREELANDER I; ROVER 75, 75 I 2.0D 02.99-10.06

Dimenzija: 150.0 mm/ ·142.0 mm | Prečnik 2: 142.0 mm | Širina: 46.0 mm | Broj rebara: 5.0 kom |
Šifra proizvoda: IC-F86835

OE Šifre

| | |
|-----------------|------------|
| 80000366 | CORTECO |
| DPV1073 | DAYCO |
| TVD1068 | GATES |
| 2156038 | SASIC |
| 11 23 2 247 887 | BMW |
| LHG100750 | FSO |
| LGH100750L | LAND ROVER |
| LHG 100750 L | LAND ROVER |
| LGH100750 | ROVER |
| LHG 100 750 | ROVER |

Ovlašćeni Servis doo

Bulevar JNA 172, 11010, Beograd

☎ 069/3467-928

Online prodavnica

<https://ovlasceniservis.com/>



NBS IPS QR